20001



Michael O. Leavitt

Lowell P. Braxton

Division Director

Governor

# State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

## **INSPECTION REPORT**

upl

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340

801-359-3940 (Fax)

801-538-7223 (TDD)

Partial: XXX Complete: Exploration:

Inspection Date & Time: 1/18/2000 / 8:10a.m.-11:15a.m.

Date of Last Inspection: 12/15/99

Mine Name: Willow Creek Mine County: Carbon Permit Number: ACT/007/038						
Permittee and/or Operator's Name: Plateau Mining Corporation						
Business Address: 847 Northwest Highway 191, Helper, Utah 84526						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Johnny Pappas						
State Officials(s): Peter Hess Federal Official(s): None						
Weather Conditions: Raining, Snow at higher elevations						
Existing Acreage: Permitted-14,670 Disturbed-161.55 Regraded- Seeded- Bonded-						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/Inactive/_ Temporary Cessation/_ Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

## REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

#### Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

1. 2. 3.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS TOPSOIL HYDROLOGIC BALANCE:	EVALUATED [XX] [XX] [XX]	<u>N/A</u> ∐ ∐ ∐	COMMENTS [XX]  L]	NOV/ENF
a. b. c. d.	DIVERSIONS SEDIMENT PONDS AND IMPOUNDMENTS OTHER SEDIMENT CONTROL MEASURES	[XX] [XX] []		[] [XX] [] []	
5. 6. 7. 8. 9.	EXPLOSIVES DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS NONCOAL WASTE PROTECTION OF FISH, WILDLIFE AND		IXXI IXXI III III		
10. 11. 12. 13. 14. 15.	RELATED ENVIRONMENTAL VALUES SLIDES AND OTHER DAMAGE CONTEMPORANEOUS RECLAMATION BACKFILLING AND GRADING REVEGETATION SUBSIDENCE CONTROL CESSATION OF OPERATIONS ROADS:		[XX] [XX] [XX] [XX] [XX] []		
a.	CONSTRUCTION/MAINTENANCE/SURFACING DRAINAGE CONTROLS OTHER TRANSPORTATION FACILITIES SUPPORT FACILITIES/UTILITY INSTALLATIONS AVS CHECK (4th Quarter-April, May, June)(date) AIR QUALITY PERMIT BONDING & INSURANCE	[XX] [XX] [XX] []			

#### **INSPECTION REPORT**

(Continuation sheet)

Page <u>2</u> of <u>3</u>

PERMIT NUMBER: ACT/007/038

DATE OF INSPECTION: 1/18/2000

## (Comments are Numbered to Correspond with Topics Listed Above)

## 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

Mr. Pappas informed me that in conversing with Mr. Mike Herkimer of the Utah DEQ/Division of Water Quality, the new UPDES permit which will be issued for the site will be a "general" permit with a five year duration period.

It is unknown at this time if the dewatering of the "K" seam workings will be necessary. This is a Corporate decision which will be made at a later time. Should it be determined necessary, Mr. Pappas will have the necessary salt mitigation plan in place with the NCRS, and a site specific UPDES permit which will allow discharging of the "K" seam water to the Price River.

#### 4b. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

New sediment level/maximum mine water elevation markers have been installed in the following ponds; 012B, 013A, and 011A. The red painted zones on the vertical pipes are indicative of the 60% cleanout level. 100% levels are indicated by the white/black demarcation. The yellow/black demarcations are indicative of the maximum allowable mine water elevation which can be contained in the pond, such that the ponds that store mine water will also still contain the design event.

The raw water process pond was overflowing this day to the Price River.

Pond 011A is in need of more cleaning. As noted above, a new sediment level marker has been installed. During today's inspection, the red/white demarcation line which designates the sixty percent cleanout elevation was below the water's surface. Mr. Pappas is fully aware that more material needs to be removed. This will not be possible until the ground freezes or the pond dries out.

#### 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

As noted last month, the permittee is scalping material from the School House Canyon refuse pile for addition to the clean coal product to enhance ash fusion temperature requirements of various coal contracts. Reject from the "scalping" process is then spread and recompacted back into the School House pile. This indicates that double processing of material is inevitable. It is recommended that the permittee look at disposing of this scalp reject in some other area of the School House pile.

At present, the permittee is not stockpiling any of the processed material in any areas of the lower plant yard. It is being used as fast as it can be hauled from the upper storage pile.

### **INSPECTION REPORT**

(Continuation sheet)

Page <u>3</u> of <u>3</u>

PERMIT NUMBER: ACT/007/038

DATE OF INSPECTION: 1/18/2000

(Comments are Numbered to Correspond with Topics Listed Above)

16b. ROADS: DRAINAGE CONTROLS

The area in and around the refuse truck loading area is and has always been a quagmire when wet conditions prevail. A change in surface configuration may be possible here to make water report to pond 011A.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Johnny Pappas (Plateau) Henry Austin (OSM)
Given to: Pam Grubaugh-Littig (DOGM)
Date: January 19, 2000

Inspector's Signature: #46

Peter Hess